



City of Urbana, Illinois Surface Water Quality Report 2016



City of Urbana 400 South Vine Street, Urbana, IL 61801
Public Works Department 706 South Glover Street, Urbana, IL 61802
<http://urbanaininois.us>
<http://www.facebook.com/CityofUrbana>

Background

The City of Urbana's Sustainable Water Management Plan calls for reporting of state and federal water quality sampling results as those results become available. The data summarized in this report is collected from the Illinois Environmental Protection Division's (IEPA) Illinois Integrated Water Quality Report and Section 303(d) List (IR) draft posted on February 11, 2016.

IEPA generally posts a draft IR on their website every other Spring. IEPA submits this report to the U.S. Environmental Protection Division (US EPA) for approval following public comment. IEPA uses the draft data for decision making since it is the most recent. This report will follow the posting of the draft data and treat it as authoritative for the same reason.


Based on IEPA's 5-year rotation schedule, streams in the Vermilion River basin are scheduled for sampling in 2016. Sites and segments to be sampled have not been selected at this time. No surface waters in the City of Urbana have Total Maximum Daily Loads established.

US EPA Water Status

IEPA re-issues the IR every other year. However, IEPA is not able to sample every surface water every two years. The most recent sampling events for surface waters in the City of Urbana are listed below.

Surface Water	Most Recent Sampling Date
Boneyard Creek - IL_BPJCA	2006
Crystal Lake - IL_RBU	2014*
Saline Branch - IL_BPJC-06	2013
Saline Branch - IL_BPJC-08	2011

*IEPA states that fish tissue samples were taken by the Illinois Department of Natural Resources in 2014, but water samples have not been taken since 1989. The reason for this is unknown. Staff has requested that Crystal Lake be added to the regular sampling regime.



Surface Water	Designated Uses	Status	Cause	Source
Boneyard Creek IL_BPJCA	Aquatic Life	Not Supporting	Alteration in stream-side or littoral vegetative covers, Copper, Dissolved Oxygen, Total Phosphorus	Channelization, Urban Runoff/Storm Sewers
	Fish Consumption	Not Assessed		
	Primary Contact	Not Assessed		
	Secondary Contact	Not Assessed		
Crystal lake IL_RBU	Aesthetic Quality	Not Assessed	Mercury	Atmospheric Deposition - Toxics
	Fish Consumption	Not Supporting		
	Primary Contact	Not Assessed		
	Secondary Contact	Not Assessed		
Saline Branch IL_BPJG-06	Aesthetic Quality	Not Assessed	N/A	N/A
	Fish Consumption	Not Assessed		
	Secondary Contact	Not Assessed		
	Aesthetic Quality	Fully Supporting		
Saline Branch IL_BPJG-08	Aquatic Life	Not Supporting	Alteration in stream-side or littoral vegetative covers, Dissolved oxygen, pH, Loss of instream cover	Channelization
	Fish Consumption	Not Assessed		
	Primary Contact	Not Assessed		
	Secondary Contact	Not Assessed		
	Aesthetic Quality	Fully Supporting		